
01272.020596 NOV ?





IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

YASUTOMO WATANABE

Appln. No.: 10/617,043

Filed: July 11, 2003

In re Patent of:

For: PRINTING HEAD AND INK JET

PRINTING APPARATUS WHICH PERFORMS PRINTING WITH THE

PRINTING HEAD

Examiner: Raquel Yvette Gordon

Group Art Unit: 2853

Patent No.: 6,935,726 B2

Issued: August 30, 2005

November 30, 2005

of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/01/2005 CNGUYEN 00000056 6935726

01 FC:1811

100.00 OP

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentee

Douglas W. Pinsky Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DWP/Iw

DC_MAIN 221428v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,935,726 B2

DATED

August 30, 2005

INVENTOR(S) :

YASUTOMO WATANABE

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 19, "ink" should read --ink .--.

COLUMN 3

Line 24, "shorten" should read --shortened--.

Line 30, "wiring line" should read -- the wiring lines--.

COLUMN 4

Line 15, "part" should read --parts--.

COLUMN 6

Line 28, "most part" should read --most--.

Line 39, "makes" should read -- make--.

COLUMN 7

Line 1, "portion" should read --portions--.

Line 8, "fashion" should read --fashion.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DWP/Iw 221430v1

PATENT NO. 6,935,726 B2

No. of add'l. copies @ 30¢ per page

DEC 5 2005

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,935,726 B2

DATED

August 30, 2005

INVENTOR(S) :

YASUTOMO WATANABE

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN₁

Line 19, "ink" should read --ink.--.

COLUMN 3

Line 24, "shorten" should read --shortened--.

Line 30, "wiring line" should read -- the wiring lines--.

COLUMN 4

Line 15, "part" should read --parts--.

COLUMN 6

Line 28, "most part" should read --most--.

Line 39, "makes" should read -- make--.

COLUMN 7

Line 1, "portion" should read --portions--. Line 8, "fashion" should read --fashion.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DWP/Iw 221430v1

PATENT NO. 6,935,726 B2

No. of add'i. copies @ 30¢ per page

DEC 5 2085

